

COMMITMENT TO QUALITY

Bigge management considers that a prerequisite to a successful operation is commitment to quality. To achieve this goal, it is essential that we have:

1. A comprehensive Quality Assurance Program which fulfills the requirements of 10 CFR 50, Appendix B, Quality Assurance Criteria for Nuclear Power Plants, and ANSI N45.2, Quality Assurance Program Requirements for Nuclear Power Plants, and a program which sets forth how our work is accomplished and controlled.
2. Quality Assurance Organizations with responsibility for the implementation of the Quality Assurance Program, and for ensuring strict compliance with its established methods.
3. An understanding by Bigge personnel that the success of a Quality Assurance Program depends on the commitment of each project and office personnel who have an impact on quality.

The authority and responsibility to establish, direct and control the Bigge Quality Assurance Program is hereby delegated to the Bigge Quality Assurance Manager. The Quality Assurance Manager is organizationally independent of production and operating personnel for nuclear projects. Conflicts in the interpretation of this manual, which cannot be resolved by the Quality Assurance Manager, shall be brought to the attention of the Vice President, Major Projects for immediate resolution.

Date

Weston J. Settlemier
President
BIGGE CRANE AND RIGGING CO.

TABLE OF CONTENTS

COMMITMENT TO QUALITY

INTRODUCTION

SECTIONS (QAMS)

- 1.0 Organization
- 2.0 Quality Assurance Program
- 3.0 Design Control
- 4.0 Procurement Document Control
- 5.0 Instructions, Procedures, and Drawings
- 6.0 Document Control
- 7.0 Control of Purchased Items and Services
- 8.0 Identification and Control of Items
- 9.0 Control of Special Processes
- 10.0 Inspection
- 11.0 Test Control
- 12.0 Control of Measuring and Test Equipment
- 13.0 Handling, Storage, and Shipping
- 14.0 Inspection, Test, and Operating Status
- 15.0 Control of Nonconforming Items
- 16.0 Corrective Action
- 17.0 Quality Assurance Records
- 18.0 Audits